

From: [THOMS Bryn](#)
To: (b) (6)
Cc: [Chip Humphrey/R10/USEPA/US@EPA](#); [ANDERSON Jim M](#); [Michael Boykin/R10/USEPA/US@EPA](#)
Subject: RE: Possible Antifreeze Spill at Schnitzers International Slip
Date: 09/29/2011 10:01 PM

Thanks. I cc'd Mike Boykin (EPA duty officer). He contacted USCG to see if they were going to respond. I'm still waiting for an update from BES.

Cell – (b) (6) or you can page me through OERS 800-452-0311.

From: William Egan [mailto:(b) (6)]
Sent: Thursday, September 29, 2011 9:54 PM
To: humphrey.chip@epamail.epa.gov; [ANDERSON Jim M](#); [THOMS Bryn](#)
Subject: Possible Antifreeze Spill at Schnitzers International Slip

While collecting fish samples for the City and the EPA about 6:30 noticed what I thought at first was an algae bloom, then I observed what seemed to be antifreeze coming from a discharge pipe about 5 gallons a minute but, as it spread quickly it could have been much more. Will look again tomorrow when we resume fishing, called 911 to contact coast guard and called BES hot line to report spill. Photos to follow.